# **Annual Environmental Report**





Greystones

D0010-01

#### **CONTENTS**

#### 1 EXECUTIVE SUMMARY AND INTRODUCTION TO THE 2023 AER

- 1.1 ANNUAL STATEMENT OF MEASURES
- 1.2 TREATMENT SUMMARY
- 1.3 ELV OVERVIEW
- 1.4 LICENSE SPECIFIC REPORT INCLUDED IN AER

#### 2 TREATMENT PLANT PERFORMANCE AND IMPACT SUMMARY

- 2.1 GREYSTONES WWTP TREATED DISCHARGE
  - 2.1.1 INFLUENT SUMMARY GREYSTONES WWTP
  - 2.1.2 EFFLUENT MONITORING SUMMARY GREYSTONES WWTP
  - 2.1.3 AMBIENT MONITORING SUMMARY FOR THE TREATMENT PLANT DISCHARGE
  - 2.1.4 OPERATIONAL REPORTS SUMMARY FOR GREYSTONES WWTP
  - 2.1.5 SLUDGE/OTHER INPUTS TO GREYSTONES WWTP

#### **3 COMPLAINTS AND INCIDENTS**

- 3.1 COMPLAINTS SUMMARY
- 3.2 REPORTED INCIDENTS SUMMARY
  - 3.2.1 SUMMARY OF INCIDENTS
  - 3.2.2 SUMMARY OF OVERALL INCIDENTS
- 4 INFRASTRUCTURAL ASSESSMENT AND PROGRAMME OF IMPROVEMENTS
  - 4.1 STORM WATER OVERFLOW IDENTIFICATION AND INSPECTION REPORT
    - 4.1.1 SWO IDENTIFICATION AND INSPECTION SUMMARY REPORT
  - 4.2 REPORT ON PROGRESS MADE AND PROPOSALS BEING DEVELOPED TO MEET THE IMPROVEMENT PROGRAMME REQUIREMENTS
    - 4.2.1 Specified Improvement Programme Summary
    - 4.2.2 IMPROVEMENT PROGRAMME SUMMARY
    - 4.2.3 SEWER INTEGRITY RISK ASSESSMENT

#### 5 LICENCE SPECIFIC REPORTS

- 5.1 PRIORITY SUBSTANCES ASSESSMENT
- 5.2 TOXICITY OF FINAL EFFLUENT

#### 6 CERTIFICATION AND SIGN OFF

6.1 SUMMARY OF AER CONTENTS

#### 7 APPENDIX

7.1 Ambient monitoring summary

# **1 EXECUTIVE SUMMARY AND INTRODUCTION TO THE 2023 AER**

This Annual Environmental Report has been prepared for D0010-01, Greystones, in Wicklow in accordance with the requirements of the wastewater discharge licence for the agglomeration. Specified reports where relevant are included as an appendix to the AER.

# **1.1 ANNUAL STATEMENT OF MEASURES**

A summary of any improvements undertaken is provided where applicable.

There were no capital works, significant changes or operational changes undertaken in 2023.

## **1.2 TREATMENT SUMMARY**

The agglomeration is served by a wastewater treatment plant(s)

• Greystones WWTP with a Plant Capacity PE of 40000, the treatment type is 2 - Secondary treatment.

# **1.3 ELV OVERVIEW**

The overall compliance of the final effluent with the Emission Limit Values (ELVs) is shown below. More detailed information on the below ELV's can be found in Section 2.

Discharge Point Reference	Treatment Plant	Discharge Type	Compliance Status	Parameters failing if relevant
TPEFF3400D0010SW001	Greystones WWTP	Treated	Compliant	N/A

# **1.4 LICENCE SPECIFIC REPORTING**

Assessment / Report

There are no Licence Specific Reports included in this AER.

# **2 TREATMENT PLANT PERFORMANCE AND IMPACT SUMMARY**

# **2.1 GREYSTONES WWTP - TREATED DISCHARGE**

### 2.1.1 INFLUENT MONITORING SUMMARY - GREYSTONES WWTP

A summary of influent monitoring for the treatment plant is presented below. This monitoring is primarily undertaken in order to determine the overall efficiency of the plant in removing pollutants from the raw wastewater.

Parameters	Number of Samples	Annual Max	Annual Mean
Suspended Solids mg/l	12	2702	313
COD-Cr mg/l	12	1033	573
BOD, 5 days with Inhibition (Carbonaceous) mg/l	12	360	155
Hydraulic Capacity	N/A	24612	9411

If other inputs in the form of sludge / leachate are added to the WWTP then these are included in Section 2.1.5 if applicable.

### Significance of Results:

The annual mean hydraulic loading is less than the peak Treatment Plant Capacity. The annual maximum hydraulic loading is greater than the peak Treatment Plant Capacity. Further details on the plant capacity and efficiency can be found under the sectional 'Operational Performance Summary'. The design of the wastewater treatment plant allows for peak values and therefore the peak loads have not impacted on compliance with Emission Limit Values.

### 2.1.2 EFFLUENT MONITORING SUMMARY - TPEFF3400D0010SW001

Parameter	WWDL ELV (Schedule A)	ELV with Condition 2 Interpretation included Note 1	Interim % reduction from influent concentration	Number of sample results	Number of exceedances	Number of exceedances with Condition 2 Interpretation included	Annual Mean	Overall Compliance (Pass/Fail)
COD-Cr mg/l	125	250	N/A	12	N/A	N/A	38	Pass
Suspended Solids mg/l	35	87.5	N/A	12	N/A	N/A	9.38	Pass
BOD, 5 days with Inhibition (Carbonaceous) mg/l	25	50	N/A	12	N/A	N/A	4.06	Pass
pH pH units	6	9	N/A	12	N/A	N/A	7.60	Pass
Enterococci (Intestinal) cfu/100ml	N/A	N/A	N/A	4	N/A	N/A	23292	
Dissolved Inorganic Nitrogen (as N) mg/l	N/A	N/A	N/A	12	N/A	N/A	20	
Total Nitrogen mg/l	N/A	N/A	N/A	12	N/A	N/A	27	
E. Coli cfu/100ml	N/A	N/A	N/A	4	N/A	N/A	70171	

Notes:

1 – This represents the Emission Limit Values after the Interpretation provided for under Condition 2 of the licence is applied 2 - For pH the WWDA specifies a range of pH 6 - 9

### **Cause of Exceedance(s):**

Not applicable

### Significance of Results:

The WWTP is compliant with the ELV's set in the Wastewater Discharge Licence.

# 2.1.3 AMBIENT MONITORING SUMMARY FOR THE TREATMENT PLANT DISCHARGE TPEFF3400D0010SW001

A summary of monitoring from ambient monitoring points associated with the wastewater discharge is provided in the sections below. For discharges to rivers upstream (U/S) and downstream (D/S) location data is provided. For other ambient points in lakes, coastal or transitional waters, monitoring data from the most appropriate monitoring station is selected.

The table below provides details of ambient monitoring locations and details of any designations as sensitive areas.

Ambient Monitoring Point from WWDL (or as agreed with EPA)	Irish Grid Reference	River Station Code	Bathing Water	Drinking Water	FWPM	Shellfish	WFD Status
Downstream	331055, 211580	CW34001016DB6014	Yes	No	No	No	High

The results for ambient results and / or additional monitoring data sets are included in the Appendix 7.1 - Ambient Monitoring Summary.

### Significance of Results:

The coastal/transitional ambient monitoring results meet the required EQS. The EQS relates to the Oxygenation and Nutrient Conditions set out in the Surface Water Regulations 2009.

The WWTP discharge was compliant with the ELV's set in the wastewater discharge licence.

The discharge from the wastewater treatment plant does not have an observable impact on the water quality.

The discharge from the wastewater treatment plant does not have an observable negative impact on the Water Framework Directive status.

The discharge from the wastewater treatment plant does not have an observable impact on the bathing water quality.

### 2.1.4 OPERATIONAL PERFORMANCE SUMMARY - GREYSTONES WWTP

### 2.1.4.1 Treatment Efficiency Report - Greystones WWTP

Treatment efficiency is based on the removal of key pollutants from the influent wastewater by the treatment plant. In essence the calculation is based on the balance of load coming into the plant versus the load leaving the plant. The efficiency is presented as a percentage removal rate.

A summary presentation of the efficiency of the treatment process including information for all the parameters specified in the licence is included below:

Parameter	Influent mass loading (kg/year)	Effluent mass emission (kg/year)	Efficiency (% reduction of influent load)
SS	1133429	34538	97
cBOD	559977	14948	97
COD	2074166	140277	93

Note: The above data is based on sample results for the number of dates reported.

### 2.1.4.2 Treatment Capacity Report Summary - Greystones WWTP

Treatment capacity is an assessment of the hydraulic (flow) and organic (the amount of pollutants) load a treatment plant is designed to treat versus the current loading of that plant.

Greystones WWTP	
Peak Hydraulic Capacity (m³/day) - As Constructed	24000
DWF to the Treatment Plant (m <sup>3</sup> /day)	8000
Current Hydraulic Loading - annual max (m³/day)	24612
Average Hydraulic loading to the Treatment Plant (m³/day)	9411
Organic Capacity (PE) - As Constructed	40000
Organic Capacity (PE) - Collected Load (peak week) <sup>Note1</sup>	26712
Organic Capacity (PE) - Remaining	13288
Will the capacity be exceeded in the next three years? (Yes/No)	No

Nominal design capacities can be based on conservative design principles. In some cases assessment of existing plants has shown organic capacities significantly higher than the nominal design capacity. Accordingly plants that appear to be overloaded when comparing a collected peak load with the nominal design capacity can be fully compliant due to the safety factors in the original design.

## 2.1.5 SLUDGE / OTHER INPUTS - GREYSTONES WWTP

'Other inputs' to the waste water treatment plant are summarised in the table below.

Input type	Quantity	Unit	P.E.	% of load to WWTP	Included in Influent Monitoring (Y/N)?	Is there a leachate/sludge acceptance procedure for the WWTP?	Is there a dedicated leachate/sludge acceptance facility for the WWTP? (Y/N)
There is no Sludge and Other Input data for the Treatment Plant included in the AER.							

# **3 COMPLAINTS AND INCIDENTS**

# **3.1 COMPLAINTS SUMMARY**

A summary of complaints of an environmental nature related to the discharge(s) to water from the WWTP and network is included below.

Number of Complaints	Nature of Complaint	Number Open Complaints	Number Closed Complaints	
There were no relevant environme				

# **3.2 REPORTED INCIDENTS SUMMARY**

Environmental incidents that arise in an agglomeration are reported on an on-going basis in accordance with our waste water discharge licences. Where an incident occurs and it is reportable under the licence, it is reported to the Environmental Protection Agency through their Environmental Data Exchange Network, or in some instances by telephone. Some incidents which arise in the agglomeration are recorded by Uisce Éireann but may not be reportable under our licence for example where the incident does not have an impact on environmental performance.

A summary of reported incidents is included below.

### **3.2.1 SUMMARY OF INCIDENTS**

Incident Type	Cause	Recurring (Y/N)	Closed (Y/N)
There were no reportable incidents in 2	023.		

### **3.2.2 SUMMARY OF OVERALL INCIDENTS**

Question	Answer
Number of Incidents in 2023	0
Number of Incidents reported to the EPA via EDEN in 2023	0
Explanation of any discrepancies between the two numbers above	N/A

# **4 INFRASTRUCTURAL ASSESSMENTS AND PROGRAMME OF IMPROVEMENTS**

## 4.1 STORM WATER OVERFLOW IDENTIFICATION AND INSPECTION REPORT

A summary of the operation of the storm water overflows and their significance where known is included below:

### 4.1.1 SWO IDENTIFICATION

WWDL Name / Code for Storm Water Overflow (chamber) where applicable	Irish Grid Ref. (outfall)	Included in Schedule of the WWDL	Significance of the overflow(High / Medium / Low)	Assessed against DoEHLG Criteria	No. of times activated in 2023 (No. of events)	Total volume discharged in 2023 (m³)	Monitoring Status
SW2	330552,211254	Yes	Low Significance	Meeting Criteria	0	0	Monitored
твс	329638,212826	Yes	Low Significance	Meeting Criteria	Unknown	Unknown	Monitored*

\* Meter is currently not operational at the Rathdown WWPS.

Any TBC SWO(s) were identified as part of the on-going National SWO programme and will be updated in subsequent AER(s) once the information is confirmed.

SWO Summary	
How much wastewater discharge by metered SWOs during the year (m <sup>3</sup> )?	0
Is each SWO identified as not meeting DoEHLG Guidance included in the Programme of Improvements?	N/A
The SWO Assessment included the requirements of relevant of WWDL schedules?	Yes

#### **SWO Summary**

Have the EPA been advised of any additional SWOs / changes to Schedule C3 and A4 under Condition 1.7?

# 4.2 REPORT ON PROGRESS MADE AND PROPOSALS BEING DEVELOPED TO MEET THE IMPROVEMENT PROGRAMME REQUIREMENTS

### 4.2.1 SPECIFIED IMPROVEMENT PROGRAMME SUMMARY

A wastewater discharge licence may require a number of reports on specific subject areas to be prepared for the agglomeration in question. These reports are submitted to the EPA as part of the Annual Environmental Report. This section provides a list of the various reports required for this agglomeration and a brief summary of their recommendations.

Specified Improvement Programmes (under Schedule A and C of WWDL)	Description	Licence Schedule	Licence Completion Date	Date Expired? (N/NA/Y)	Status of Works	Timeframe for Completing the Work	Comments
D0010-SIP-01	WWTP upgrade from capacity to treat 30,000pe to 40,000pe	С	01/12/2011	Yes	Works Completed		

A summary of the status of any other improvements identified by under Condition 5 assessments- is included below.

### 4.2.2 IMPROVEMENT PROGRAMME SUMMARY

Improvement	Improvement Description / or any Operational	Improvement	Expected Completion	Comments
Identifier	Improvements	Source	Date	
No additional improve	ments planned at this time.			

### 4.2.3 SEWER INTEGRITY RISK ASSESSMENT

The utilisation of multiple capital maintenance programmes and the outputs of the workshops with the Local Authority Operations Staff held under the programme can be used to satisfy the requirements of Condition 5 regarding network integrity. Improvement works identified by way of these programmes and workshops will be included in the Improvements Summary Tables 4.2.1 and 4.2.2.

# **5 LICENCE SPECIFIC REPORTS**

A wastewater discharge licence may require a number of reports on specific subject areas to be prepared for the agglomeration in question. These reports are submitted to the EPA as part of the Annual Environmental Report. This section provides a list of the various reports required for this agglomeration and a brief summary of their recommendations.

Licence Specific Report	Required by licence	Included in this AER	
D0010-01-Priority Substances Assessment	Yes	No	
D0010-01-Toxicity of Final Effluent	Yes	No	

# **6 CERTIFICATION AND SIGN OFF**

# **6.1 SUMMARY OF AER CONTENTS**

Parameter	Answer
Does the AER include an Executive Summary?	Yes
Does the AER include an assessment of the performance of the Waste Water Works (i.e. have the results of assessments been interpreted against WWDL requirements and or Environmental Quality Standards)?	Yes
Is there a need to advise the EPA for Consideration of a Technical Amendment/Review of the Licence?	No
List reason e.g. additional SWO identified	N/A
Is there a need to request/advise the EPA of any modification to the existing WWDL with respect to condition 4 changes to monitoring location, frequency etc	No
List reason e.g. changes to monitoring requirements	N/A
Have these processes commenced?	N/A
Are all outstanding reports and assessments from previous AERs included as an appendix to this AER	N/A

I certify that the information given in this Annual Environmental Report is truthful, accurate and complete:

Date: 12/03/2024

This AER has been produced by Uisce Éireann's Environmental Information System (EIMS) and has been electronically signed off in that system for and on behalf of,

Eleanor Roche

Head of Environmental Regulation.

# **7** APPENDIX

#### Appendix

Appendix 7.1 - Ambient Monitoring Summary

## **Ambient Monitoring Data 2023**

### Ambient Monitoring Report Summary Table

Ambient Monitoring Point from WWDL (or as agreed with EPA)	Irish Grid Reference	Bathing Water	Drinking Water	FWPM	Shellfish
Within 200m radius of SW1 and within 750m of shoreline (Irish Sea)	331055E, 211580N	No, but SW001 sea outfall discharges 750m offshore from a bathing area and sea outfall SW002 420m offshore	No	No	No

#### **Greystones Outfall**

The Primary Discharge point is in the Irish Sea, 750 metres from the shore. The sampling point is within a 200 metre radius of SW1.

	Sample Date	pH pH units	BOD mg/ I	Total Nitrogen as N mg/l	Dissolved Inorganic Nitrogen as N mg/l	DO % sat	DO mg/l	E. coli cfu/100ml	Intestinal enterococci cfu
Greystones WWTP Ambient	02/10/2023	8.23	4	<0.5	0.41	100.5	10.9	16	7

### Bathing Water Results 2023 - South Beach, Greystones

Sample	E.coli	Intestinal Enterococci	
Date	Result	Result	Water Quality
04/09/2023	10	3	Excellent
28/08/2023	10	1	Excellent
21/08/2023	<10	12	Excellent
14/08/2023	<10	7	Excellent
31/07/2023	<10	5	Excellent
10/07/2023	86	37	Excellent
03/07/2023	<10	5	Excellent
19/06/2023	<10	1	Excellent
06/06/2023	<10	1	Excellent
22/05/2023	<10	3	Excellent

(Source: Beaches.ie)